

**EMSL Analytical, Inc.**

490 Rowley Road, Depew, NY 14043

Phone/Fax: (716) 651-0030 / (716) 651-0394

<http://www.EMSL.com>buffalolab@emsl.com

EMSL Order: 141805845
CustomerID: RFWE53
CustomerPO:
ProjectID: RFP 509

Attn: **Smita Sumbaly**
Weston Solutions (King Georges Post)
1090 King Georges Post Road
Suite 201
Edison, NJ 08837

Phone: (732) 585-4400
Fax:
Received: 11/02/18 4:29 PM
Analysis Date: 11/5/2018
Collected: 11/2/2018

Project: RFP No. 509 / Site #A28U / TDD # TO-0370-0100

Test Report: Asbestos Analysis of Bulk Material

| Test | Analyzed Date | Color | Non Asbestos | | Asbestos |
|-----------------------|----------------|-------------|--------------|-------------|-----------------------------|
| | | | Fibrous | Non-Fibrous | |
| Sample ID | TCBP-BULK024 | Description | BULK024 | | |
| | 141805845-0001 | Homogeneity | Homogeneous | | |
| PLM NYS 198.1 Friable | | | | | Not Analyzed |
| PLM NYS 198.6 VCM | | | | | Not Analyzed |
| PLM NYS 198.6 NOB | 11/3/2018 | Black | | | Inconclusive: None Detected |
| TEM NYS 198.4 NOB | 11/5/2018 | Black | | | None Detected |
| Sample ID | TCBP-BULK025 | Description | BULK025 | | |
| | 141805845-0002 | Homogeneity | Homogeneous | | |
| PLM NYS 198.1 Friable | | | | | Not Analyzed |
| PLM NYS 198.6 VCM | | | | | Not Analyzed |
| PLM NYS 198.6 NOB | 11/3/2018 | Black | | | Inconclusive: None Detected |
| TEM NYS 198.4 NOB | 11/5/2018 | Black | | | None Detected |

Analyst(s)

Mark Tate

Tom Hanes

Rhonda McGee, Laboratory Manager
or other approved signatory

NOB = Non Friable Organically Bound N/A = Not Applicable VCM = Vermiculite Containing Material

-In New York State, TEM is currently the only method that can be used to determine if NOB materials can be considered or treated as non-asbestos containing.

All samples examined for the presence of vermiculite when analyzed via NYS 198.1.

-NYS Guidelines for Vermiculite containing samples are available at http://www.wadsworth.org/labcert/elapcert/forms/VermiculiteInterimGuidance_Rev070913.pdf

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. Samples were received in good condition unless otherwise noted.

This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. This report may contain data that is not covered by the NVLAP accreditation.

Samples analyzed by EMSL Analytical, Inc. Depew, NY NYS ELAP 11606